
5/015/046

3809 U67-P90-03 (U-067)

Moab District San Rafael Resource Area 900 North 700 East Price, Utah 84501



DIVISION OF OIL GAS & MINING

Mr. Tom Clark Mivita Distributing Company 939 West Jewell Avenue Salt Lake City, Utah 84104

Dear Mr. Clark:

We have inspected your operation on the Daddy Dearest mining claim group and the following items need to be resolved:

- A. Junk, including an old pickup, should be removed and disposed of at an authorized landfill. Another truck should be maintained or removed.
- B. Two areas require reclamation. The first is the old access road which comes up the side of the hill to the portal. The second is up on top where an area was cleared.
- C. The old operator address of Mivita Distributing Company is apparently no longer valid. As long as an operator is active, the operator is required to maintain his current address and telephone number at the appropriate area office.

You shall inform us of your future plans within 30 days of the date of this letter. Your future plans shall include a time frame for resolving the aformentioned concerns which include reclamation and removal of junk and address changes. We can schedule an onsite inspection to discuss and resolve these problems if you are agreeable.

We will assume that the operation has been abandoned if we do not hear from you with the 30-day time period land we will then require that the operation be reclaimed.

We have enclosed a blank Notice or Plan of Operations form for your convenience.

Sincerely yours,

/S/Tom Gnojek

Area Manager

Enclosure:

Notice or Plan of Operations Form

cc: Holland Shepherd, UDOGM
Bryant Anderson, Emery County

NSimmons:ks:1/28/92

LTRCLARK